

Soldering Safely


Do not inhale solder fumes.

Maintain a safe distance and ensure proper ventilation.




To prevent burns, only touch the handle of the soldering iron.
Always place the soldering iron on the soldering stand when not in use.





Keep an eye on the **position** of the soldering iron **cable**.



Securely grip and cut off any protruding wire pieces using flat-nose pliers.

202-076